

## **Door Restrictor Statement**

Good Morning.

Effective May 1, 2011 an elevator which has a violation to repair the door restrictor shall immediately be removed from service and cannot be used until The City of Houston has received a reinspection report stating the door restrictor is operational. This violation shall be listed as A17.1 2007 Safety Code for Elevators and Escalators section 8.6.1.2.2 requires units with defective safety devices to be removed from operation. Found the door restriction means to be inoperative. The City of Houston has made this decision based on A 17.1 2007 Safety Code for Elevators and Escalators section 1.2.2.1 The specific requirements of this code shall be permitted to be modified by the authority having jurisdiction based upon technical documentation or physical performance verification to allow alternative arrangements that will assure safety equivalent to that which would be provided by conformance to the corresponding requirements of this code. If you have any questions please do not hesitate to contact me.

Mike Dorosk  
City Of Houston  
Code Enforcement  
Elevator Group  
713-535-7577 phone  
713-535-7920 fax